



Safety moment

Laser steering optics, periscopes, and stray beams



An experimental setup on a laser table can get quite complicated... always be aware of where the beam(s) are.





Periscopes are a location where extra caution is needed, since the beam is intentionally steered up/down from the table (i.e., where your eyes might be)

Scatter must be controlled with beam blocks or (preferably) beam dumps.

